
Storage tank on Fire

EPSC Learning Sheet - April 2018

What Happened:

A storage tank with an inner floating roof got on fire while being loaded from a tanker with gasoline.






EPSC

Aspects to discuss:

- ➤ Floating roof of flammable liquid storage tanks are zone 0, that require elimination of all ignition sources
- > Hydrocarbons can accumulate here and need to be vented
- ➤ In this incident, it seems that a spark generated around the floating roof seal started the fire
- ➤ Check seal performance with e.g. an explosion meter or FLIR
- ➤ Assure that the internal floating roof is well bonded
- ➤ Minimise trembling & static charging due to gas bubbles from filling, by inlet pipe design



- ➤ Automatic extinguishment of rim fires is good practice
- ➤ Good design and fire protection needs to avoid domino effects from heat radiation, use QRA and apply safe distances

Avoid fires on floating roof tanks

EPSC Learning Sheets are meant to stimulate awareness and discussion on Process Safety
EPSC can not be hold liable for the use of this sheet

Questions or Contact via www.EPSC.be