## Safety system not working

**EPSC Learning Sheet July 2022** 



Bhopal: Flare was not working (this was known)



Chernobyl: Emergency stop did not work (design flaws were known)

**EPSC** 



Ski-lift Italy: Emergency break was bypassed (on purpose)



Macondo oil rig: Blow-out preventor failed



## **Aspects:**

➤ A solid last line of defence, like SIL rated interlocks, Pressure relieve devices and Passive barriers, are essential for scenario's that involve multiple fatalities. Assure high reliability by a good design, preventive maintenance and regular testing.

A last line of defence, that prevents multiple fatalities, has to work

EPSC Learning Sheets are meant to stimulate awareness and discussion on Process Safety
EPSC can not be held liable for the use of this sheet

Questions or Contact via WWW.EPSC.be